



Case Study

Over the years, the owners of this private property in the North West of England, had used various different jointing products to repair the failed pointing on their stone sett driveway. Unfortunately, all had failed. Seeking a lasting solution, the homeowners contacted specialist paving contractor, CR Services, who together with their material consultants and distributors, NCC Streetscape, decided that GftK vdw 850plus, the state of the art, 2-part epoxy paving joint mortar was the ideal re-pointing product.

GftK vdw 850plus is a high performance, non-staining, 2-part epoxy paving mortar, supplied exclusively by NCC Streetscape. It is extremely tough and durable - ideal for patios and driveways, designed to withstand the stress and loadings caused by the homeowners vehicles

The old, failed pointing was removed, the driveway was jet washed and then treated with NCC Black Spot & Green Growth Remover to remove green growths and dirt, including the blackspot deposits largely caused by lichens. The driveway was then re-pointed with GftK vdw 850plus, using wet slurry techniques from a standing position. GftK vdw 850plus effectively self-compacts into the joints, making the whole operation quick and efficient.

The completed driveway now looks immaculate, and with just periodic jet-washing, which GftK vdw 850plus is fully resistant to, will remain so for years to come, making the homeowners extremely happy!



Pavement Jointing Mortars



01257 266696

