



Riven Sandstone Patio & Terraces, Glossop, Derbyshire

Case Study

This charming old cottage, in Glossop, the High Peak district of Derbyshire, has 170m² of traditional old riven sandstone paving, up to 70mm thick, not unlike Yorkstone. Some areas are also used as hard standing for motor vehicles. The paving had been down for many years, and was in an extremely tired condition, with some missing slabs, old cracked and failing cement based joint repairs, together with dirt, grime, moss and lichen build up on the surfaces.

After online research, the homeowners contacted specialist paving contractor, CR Services, who together with their materials supplier, NCC Streetscape, recommended replacing the failed jointing with GftK's vdw 850+, a professional, high performance, 2-part paving joint mortar, which is applied by wet slurry techniques from a standing position, making the process fast and efficient. It can also be applied in wet and cold conditions, meaning far less delays because of the weather.

Prior to grouting, missing slabs were replaced, loose slabs were reset, and the area was jet-washed and cleaned, using NCC Black Spot & Green Growth Remover, which removed dirt, grime and unsightly green stains, plus hard to remove black lichen spots.

The delighted homeowners can now safely use the area which can easily be kept clean, and without fear of damage from vehicle movements and regular jet-washing.

Garden Patios & Pathways

Client:

Private Residence

GftK Products Used:

vdw 850+ Natural

Paving Contractor:

CR Services

Call NCC Streetscape

01257 266696

www.nccstreetscape.co.uk

