

Sandstone Driveway, Warrington

Case Study

The homeowner of this property in Warrington was so impressed with the new grouting carried out on her decorative sandstone patio by specialist paving contractor, CR Services, that she re-engaged him to refurbish and repoint her sandstone driveway.

The original compound grouting was failing so CR Services recommended Gftk's vdw 850+, a non-staining 2-part epoxy paving mortar from NCC Streetscape, that is extremely tough and durable - ideal for both patios and driveways. It is applied by wet slurry techniques in a comfortable standing position, effectively self compacting into the joints with no additional tooling, so the whole operation is both quick and clean. A major advantage of vdw 850+ is that it can be applied in the wet and cold, so no waiting around for the weather - a huge plus in the UK!

Prior to grouting, the old failed jointing was raked out and all areas were jet-washed and thoroughly cleaned using NCC Black Spot & Green Growth Remover, also supplied by NCC Streetscape, which removes unsightly green staining and hard to remove lichen deposits.

The homeowner was delighted with her finished patio and in particular her driveway, which she can now use safely without fear of inflicting any damage from the vehicle movements.

Domestic Driveway

Client:

Private Residence

GftK Products Used:

vdw 850+ Stone Grey

Paving Contractor:

CR Services

Call NCC Streetscape

01257 266696

www.nccstreetscape.co.uk

GftK

Pavement Jointing Mortars

