



Sandstone Driveway & Patio, Eccles, Greater Manchester

Domestic Driveway

Client:

Private Residence

GftK Products Used:

vdw 850+ Natural

Paving Contractor:

CR Services

Call NCC Streetscape

01257 266696

www.nccstreetscape.co.uk

Case Study

The weather forecast for the December time period booked for the refurbishment of this large natural sandstone driveway and patio was cold and wet, but luckily the homeowners had chosen GftK's vdw 850+ paving mortar from NCC Streetscape to replace the original mixture of single pack jointing compound and cement based grouting that was now cracked and failing. GftK's vdw 850+, is a professional 2-part, tough and durable, 2-part epoxy resin paving mortar which is applied by wet slurry techniques from a standing position and importantly in Winter, the work can still be carried out in cold and wet conditions - in fact the wetter the better!

The team from specialist paving contractors CR Services, employed to carry out the work, removed the failing grout mortars and cleaned all of the paving surfaces with NCC Black Spot & Green Growth Remover, which does exactly as it says on the tin, removing any unsightly green growth and the difficult to clean and remove black lichen spots.

Although it rained for nearly the whole time, CR Services completed the application with vdw 850+, covering the whole area of around 250m², remarkably quickly and on schedule. The homeowners were so pleased with the result that they recommended GftK's vdw 850+ to a neighbour, who took their advice, and also employed CR Services to do a similar job to refurbish their paving.

